

# GUNTHER WEISS SCIENTIFIC

## PREFIX GUIDE

**1** **0 0 0 0** - **X X X X** = Jones Tube  
CLASS      ATTRIBUTES      MEASUREMENT

1 X X X X - X X X X = Jones Tube

0 0 0 1 - X X X X = No Bevel

0 0 1 0 - X X X X = Angled

0 1 0 0 - X X X X = Frosted

1 0 0 0 - X X X X = Suture Hole

3 0 X X = 3.0mm (diameter)

X X 2 0 = 20mm (length)  
DIAMETER      LENGTH